

JUL 31 1974
#582/ 37138

| | | | | | |
|---|--------------------------------------|---|-----|----------|-----------|
| 2-3) ST | 4-16) NJ 0002L29 PERMIT NUMBER | 17-19) DIS | SIC | LATITUDE | LONGITUDE |
| REPORTING PERIOD: FROM | | TO | | | |
| (20-21) (22-23) 24-25) 1974 June 1 st YEAR MO DAY | | (26-27) (28-29) (30-31) 1974 July 1st YEAR MO DAY | | | |

| PARAMETER | | (3 card only) QUANTITY | | | | UNITS |
|------------------------|---------------------|---------------------------|--|--------------------|--|-------|
| | | (38-45) MINIMUM | (46-53) AVERAGE | (54-61) MAXIMUM | | |
| pH | REPORTED | | | | | |
| | PERMIT CONDITION | | 6 | 11 | | |
| Temperature | REPORTED | | | | | |
| | PERMIT CONDITION | | | | | |
| Total Suspended Solids | REPORTED | | 17,300 gal @ 118 ppm 6500 gal/day @ 8.3 ppm | | | |
| | PERMIT CONDITION | | | | | |
| | REPORTED | | | | | |
| | PERMIT CONDITION | | | | | |
| | REPORTED | | | | | |
| | PERMIT CONDITION | | | | | |
| | REPORTED | | | | | |
| | PERMIT CONDITION | | | | | |
| | REPORTED | | | | | |
| | PERMIT CONDITION | | | | | |
| | REPORTED | | | | | |
| | PERMIT CONDITION | | | | | |

| | | | | | | |
|-------------------------------------|--------|----|----------------------|--|------|-----------|
| NAME OF PRINCIPAL EXECUTIVE OFFICER | | | TITLE OF THE OFFICER | | DATE | |
| Reilly | George | F. | Plant Manager | | 1974 | July 29th |
| LAST | FIRST | MI | TITLE | | YEAR | MO DAY |

ASB 001 0959

1. Provide dates for period covered by this report in spaces marked "REPORTING PERIOD".
2. Enter reported minimum, average and maximum values under "QUANTITY" and "CONCENTRATION" in the units specified for each parameter as appropriate. Do not enter values in boxes containing asterisks. "AVERAGE" is average computed over actual time discharge is operating. "MAXIMUM" and "MINIMUM" are extreme values observed during the reporting period.
3. Specify the number of analyzed samples that exceed the maximum (and/or minimum as appropriate) permit conditions in the columns labeled "No. Ex." If none, enter "0".
4. Specify frequency of analysis for each parameter as No. analyses/No. days. (e.g., "3/7" is equivalent to 3 analyses performed every 7 days.) If continuous enter "CONT."
5. Specify sample type ("grab" or "— hr. composite") as applicable. If frequency was continuous, enter "NA".
6. Appropriate signature is required on bottom of this form.
7. Remove carbon and retain copy for your records.
8. Fold along dotted lines, staple and mail Original to office specified in permit.

ASB 001 0960